






Art. Nr. 9945 4722






LKZ 41164



- | | |
|---|-------------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montazu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrukțiuni de montaj |
| (TR) Montaj talimati | (RU) Инструкция по монтажу |





A 090913  7x32 x26	B 000146  15x12 x26	C 000151  8x35 x18	D 100640  20x0.5 x8	E 193080  L300 x2	F 235593  6x8 x8
G 000767  3x13 x12	H 101608  7x50 x4	I 135021  x4	J 000759  3x20 x4	K 007085  M6 x4	L 216009  M6x12 x8
M 179404  M6x30 x8	N 230041  22x16 x4	O 238966  inosegn x1			




N	LxBxH (mm)	Qty	✓	N	LxBxH (mm)	Qty	✓
1	356x115x16	1		8	1024x114x16	1	
2	356x115x16	1		9	322x97x16	1	
3	300x75x16	2		10	1024x322x16	1	
4	300x75x16	2		11	1100x400x16	1	
5	481x75x16	2		12	922x280x16	1	
6	509x111x16	1		13	457x310x3	2	
7	509x111x16	1		14	604x167x30	4	

Service - Dienstverlening - Serwis - Servis - Сервисная служба

Name - Naam - Nazwa - Isim - Название

Nr. - No. - Номер

Typ - Type - Tip - Тип



1


x2

B
000146



15x12


x4



2


x2

A
090913




7x32

x4




3

x2

H
101608 7x50
x4


4

x2




5


5 x2




6 x2






E		L300
193080		x2
G		3x13
000767		x8
I		
135021		x4
J		3x20
000759		x4






7

A		7x32	B		15x12	C		8x35
090913		x4	000146		x6	000151		x6





8

B		15x12	C		8x35
000146		x8	000151		x8





9

A
090913 7x32
x2





10

A
090913 7x32
x10





11

A		7x32	B		15x12	C		8x35
090913		x6	000146		x8	000151		x4




12


E		L300	F		6x8	G		3x13
193080		x2	235593		x4	000767		x2




13



14




15



16


E		L300	F		6x8	G		3x13
193080		x2	235593		x4	000767		x2



17


x4

K	M6
007085	 x4
N	22x16
230041	 x4




18

M	M6x30
179404	 x8




19



216009 L M6x12 x8

20



13

